



IH 45 – Huntsville, TX

Managing Project Changes



April 12, 2024

Table of contents



1	Parties Involved	3
2	Field Decisions	4
3	Revising Safety Measures	6-7
4	TxDOT / 3 rd Party Requested	8-9
5	Error and Omissions	10
6	Unforeseen Condition	11-12
7	Key Points	13



- Contractor
- Huntsville Area Office
- CEI
- Design Consultant



- Overruns or Underruns (That don't require CO)
 - Major / Non Major items
 - Plans Quantity
- Place Adjustment
- Cap an inlet to maintain drainage.






- Revising Safety Measures
- Error & Omission
- TxDOT Requested
- 3rd party requested
- Unforeseen Conditions



- Workers
 - Add Soil Nail Wall Barrier Protection (CO #8)





- Traveling Public
 - Add Warning Signs (CO #3)
 - Add Low Profile (CO #4)





- TxDOT requested Change
 - Additional Pavement
 - Temp Signal (CO #36)

3rd Party Requested




- 3rd Party Requested Change
 - Crash Cushion Repair and replacements





Error and Omission





- Weather
 - Ice
 - Time or Days
 - Major Rain Event
 - Maintenance or replacement of SW3P devices





- Utility
 - Retaining Wall #18





- Relationship between all parties
- Record keeping
- Keep everyone informed

